FORM: OM-687 December 1998

Three-Phase Running Gear (042 886), Weld Cable Holder (043 055), Cylinder Rack/Lift (043 005), And Stationary Cylinder Rack (042 887)

### WARNING

# Ż

#### **ELECTRIC SHOCK can kill.**

- Do not touch live electrical parts.
- Turn Off welding power source and input disconnect device.
- Disconnect input power conductors from deenergized supply BEFORE moving welding power source.



#### CYLINDERS can explode if damaged.

- Keep cylinders away from welding and other electrical circuits.
- Never touch cylinder with welding electrode.
- Always secure cylinder to running gear, wall, or other stationary support.



## FALLING EQUIPMENT can cause injury and damage.

- Use proper equipment to lift unit.
- Use lifting forks long enough to extend out opposite side of base.
- Do not put any body part under unit while lifting.

  miscwarn1.1 5/9



② 3/8, 7/16, 9/16, 5/8 in






Figure 1. Installing Three-Phase Running Gear




Figure 2. Installing And Operating The Cylinder Rack/Lift




Figure 3. Parts List For Cylinder Rack/Lift




Figure 4. Installing Stationary Cylinder Rack